ENVIRONMENTAL PHOTOGRAPHIC INTERPRETATION CENTER (EPIC)

AERIAL SURVEY PRELIMINARY SITE ASSESSMENT

RESPONSE

EPIC Project Number: 91151	Request Date:12/14/90
Site Name: NAVAL FACILITY N. DIVISION CAMP HELO	Region: 2
Site/Facility Type:	
State: NY County: SUFFOLK 1	Municipality:
Iatitude: 41° 04' 00" Longitude: 71° 5	52′10"
Regional Project Manager: I	Phone# FTSCOMM
Imagery Date: September 27, 1947 Film Type: <u>BW</u>	Scale: <u> </u> :20,000
Site Active Tanks Drums Standing Liquid Ground Stains Ground Disturbance Leachate Excavation Pits Trenches Comments:	Lagoons/Impoundments Solid Waste Fill Area Pipelines Extraction Crates/Containers
Imagery Date: FEBRUARY 20, 1954 Film Type: BW	· · · · · · · · · · · · · · · · · · ·
Site Active Tanks Drums Standing Liquid Ground Stains Ground Disturbance Leachate Excavation Pits Trenches Comments:	Lagoons/Impoundments Solid Waste Fill Area Pipelines Extraction Crates/Containers
Imagery Date: MAY 17,1961 Film Type: <u>BW</u>	Scale: [:20,000
Site Active Tanks' Drums Standing Liquid Ground Stains Ground Disturbance Leachate	Solid Waste Fill Area Pipelines Extraction

Imagery Date: OCTOBEL 6, 1969 Film Type: _ f	Scale: <u>1:40,000</u>
Site Active Tanks Drums Standing Liquid Ground Stains Ground Disturbance Leachate Excavation Pits Trenches	•
Standing Liquid Ground Stains _	Solid Waste Fill Area
Ground Disturbance Leachate	Pipelines Extraction
1144 1144.4145	Crates/Containers
Comments:	
Imagery Date: September 8, 1940 Film Type: B	·
Site Active / Tanks _ Drums Standing Liquid _ Ground Stains _ Commond Districtions	s Lagoons/Impoundments
Standing Liquid Ground Stains	Solid Waste Fill Area
Ground Disturbance Leachate	Pipelines Extraction
Excavation Pits Trenches _	Crates/Containers
Comments:	
Control of the Contro	
Imagery Date: MARCH 16, 1995 Film Type: C	•
Site Active Tanks Drums Standing Liquid Ground Stains Ground Disturbance Leachate	Tagoons/Twooundments
Standing Liquid Ground Stains	Solid Waste Fill Area
Ground Disturbance Leachate	Pipelines Extraction
Excavation Pits Trenches	Crates/Containers
Comments:	
Imagery Date: Film Type:	Scale:
Site Active Tanks Drums Standing Liquid Ground Stains	Iagoons/Impoundments
Standing Liquid Ground Stains	Solid Waste Fill Area
Ground Disturbance Leachate	Pipelines Extraction
Ground Disturbance Leachate Excavation Pits Trenches	_ Crates/Containers
Comments:	
	<u> </u>
Imagery Date: Film Type:	Scale:
Site Active Tanks Drums	Lagoons/Impoundments
Standing Liquid Ground Stains	_ Solid Waste Fill Area
Ground Disturbance Leachate	Pipelines Extraction
Excavation Pits Trenches	
Comments:	

:

ADDITIONAL COMMENTS

THE SITE	15 PRESENT	ON ALL YEARS	OF PHOTOGRAPHY A	NALYZED . NO SIG	NIFICANT ACTIVITY	
	•	•	, , ,	•		
WAS NOTICED.		-				
					•	
					·	

For additional information contact:

Environmental Photographic Interpretation Center

FTS 557-3110

Commercial: (703) 349-8970

Attention: HRS Team

Naval Facility
North Division Camp Hero
Montauk, New York
EPIC Frame #32751
September 27, 1947
Approx. Scale 1:20,000



Naval Facility
North Division Camp Hero
Montauk, New York
EPIC Frame #32860
February 20, 1954
Approx. Scale 1:18,000




Naval Facility
North Division Camp Hero
Montauk, New York
EPIC Roll #32778 (308)
Frame #61
May 17, 1961
Approx. Scale 1:20,000



Naval Facility
North Division Camp Hero
Montauk, New York
EPIC Roll #32778 (308)
Frame #66
October 6, 1969
Approx. Scale 1:40,000

Naval Facility
North Division Camp Hero
Montauk, New York
EPIC Roll #32778 (308)
Frame #74
September 8, 1980
Approx. Scale 1:40,000



Naval Facility
North Division Camp Hero
Montauk, New York
EPIC Frame #33014
March 16, 1985
Approx. Scale 1:58,000